

Message

---

**From:** [Nonresponsive based on revised scope]@erllc.com]  
**Sent:** 7/14/2020 9:50:02 AM  
**To:** Wagner, Christine [Wagner.Christine@epa.gov]  
**CC:** [Nonresponsive based on revised scope]@erllc.com; [Nonresponsive based on revised scope]@acvenviro.com]  
**Subject:** Shiloh Church Road Off Spec Drums  
**Attachments:** ATT00001.txt; [Nonresponsive based on revised scope].vcf; Attachment C-Analysis WD01, WD02, WD03, WT01, WT02.PDF; Unknown drums.docx; ACV Discrepancy Notice.pdf; WD01 Profile-corrected.pdf; WD03 Profile.pdf

Chris,

Attached are the documents that you did not get? They were forwarded to you with ACV email on 7/10.


I also attached the ACV discrepancy notice QA/QC report form from ACV that we received on 7/9. I believe it is for WD01 (3 drums). It does not say at what degree it flashed.

I do not see a discrepancy QA/QC report for WD03 (1 drum), I will ask ACV about this. The waste profiles are attached for the 2 waste streams.

Keep in mind that the WD01 sample we analyzed was a composite from all 3 drums. It looks like ACV screened each drum individually.

I plan to follow up with [Nonresponsive based on revised scope] today to discuss this and request off spec info for WD03 drum and the temp that the drums flashed when they did the closed cup method. As you said we have done all the testing that they want to do for unknown drums. We actually did more testing running total VO & SVO.

I'll call later this morning after I talk to [Nonresponsive based on revised scope] and receive the additional info. Have a good day.



No job is so important and no service so urgent, that we cannot take time to perform our work safely.



Confidentiality Warning: This e-mail and any attachments contain information intended only for the use of the individual or entity named above. If the reader of this e-mail is not the intended recipient or the employee or agent responsible for delivering it to the intended recipient, any dissemination, publication or copying of this e-mail is strictly prohibited. Although this email has been scanned for malware, the sender does not accept any responsibility for any loss, disruption or damage to your data or computer system that may occur while using data contained in, or transmitted with, this e-mail. If you have received this e-mail in error, please immediately notify by return e-mail. Thank you.